

Hello,

The security mechanism of OPC-UA is the fault.

In our Version of Windows CE you cannot work with the security mechanism of OPC-UA. You have to switch off the security mechanism in your ctrlx.

Mit freundlichen Grüßen / Best regards

Peter Budsky
Application GMC Systems DC-AE/STS2

Tel. +49 6062 78-587
Fax +49 6062 78-662
Mobil +49 160 7025820
Peter.Budsky@boschrexroth.de
www.boschrexroth.com

Bosch Rexroth AG
Berliner Straße 25
64711 Erbach
GERMANY

rexroth
A Bosch Company